McMICHAEL 390

Three-valve, plus rectifier, three waveband superhet for 200-250 v., 50-100 cycles.

Circuit.—Transformer coils, having a common primary on M. and L.W. feed a TH41 frequency changer. Trimmed-tuned I.F. coils lead to a VP41 I.F. amplifier and to an AC5/Pen/ DD combined detector, A.V.C. and output valve. A full-wave UU6 rectifier operates in a conventional circuit.

Mains consumption: 60 watts. Wavebands: 18.5-50, 190-550, 850. 2,000 metres.

Provision for P.U. and 2-4 ohm extension speaker.

GANGING

I.F. Circuits.—Set gang to maximum and see that centre of pointer is in line with edge of blackened portion at top of scale. Inject 465 kc. and adjust I.F. trimmers.

S.W. Band.—Inject 16.2 mc., tune set | CONDENSERS to 18.5 m. (gang minimum) and adjust VC1.

Inject 15.3 mc., tune to 19.6 m. and adjust VC2.

M.W. Band.—Inject 1,580 kc., tune to 189.87 m. (minimum) and adjust

Inject 1,400 kc., tune to 214.28 m. and adjust VC4.

L.W. Band.—Inject 273 kc., tune to 1,100 m. and adjust VC5 and VC6.

VALVE VOLTAGES

Type	Anode	Screen	Cathode
TH41	230	110	_
VP41	230	230	
	210	230	21
UU6		_	305D,C.
	TH41 VP41 AC5/Pen/ DD	TH41 230 65(OSC VP41 230 AC5/Pen/ 210 DD	TH41 230 110 65(OSC.) VP41 230 230 AC5/Pen/ 210 230 DD

RESISTANCES

R	_	Ohm	R		Ohms
Ļ		40,000	11		40
		$.5~\mathrm{meg}$.	12		1 meg.
:		40,000	13		50,000
		50,000	14	::	.5 meg.
		100	15		1.000
		2,000	16		180
		.5 meg.	17	::	350
		.5 meg.	18		50
		.5 meg.	VR1		1 me.
		.5 meg.	VR2	• •	50,000


C	Mfds.		C Mfds.		
1 2 3 4 5		.001 .1 .004	14 15 16 17 18		
6 7 8 9 10		.1 20 mmfds. .0001 .0001 50 mmfds. 168 mmfds.	19 20 21 22 23 24		
12 13	::	507 mmfds. 3,500 mmfds.	25 26	8	

An Oscillator Fault

A NUMBER of sets of the same type came in with the same faultnot working on L.W., and only on the lower half of M.W. An oscillator fault was suspected. The frequencychanger valve was substituted without result.

A milliameter was inserted in the oscillator anode feed, and as the pointer | but, as a last resort, we had it rewas moved up the M.W. band the current | wound and impregnated. The whole was increased (signifying less oscillatory then assembled and worked perfectly, where signals ceased. It seemed that the coils were impregnated, or the forthe reaction system of the oscillator mers, had absorbed moisture and this coil was at fault.

gave satisfactory ohmmeter readings F. DAY-LEWIS, Dublin.



voltage). Current reached maximum Presumably the material with which altered the mutual inductance. The The unit was dismantled. The coil same cure was effective in all cases.--

The 390 is a "short" threevalve superhet of simple but efficient design. The chassis layout diagram above includes the trimmers, some of which are seen "through" the chassis, actually being underneath.

